

<i>Drehmoment-Adapter</i>				
Adapter	D	L	b	SW
A-M8	22	43	10	13.9
A-M10	26	43	10	13.9
A-M12	30	45	12	15.9
A-M15	33	47	12	16.9
A-M17	36	47	12	17.9
A-M20	40	50	15	18.9
A-M25	46	51	15	18.9
A-M30	53	51	15	19.9
A-M35	60	51	15	20.9
A-M40	68	51	15	21.9
A-M45	75	53	15	21.9
A-M50	80	53	15	23.9
A-M55	87	53	15	23.9
A-M60	92	53	15	23.9
A-M65	97	56	18	26.9
A-M70	104	60	18	26.9
A-M75	110	60	18	26.9
A-M80	118	60	18	26.9
A-M85	124	60	18	26.9
A-M95	145	60	18	29.9
A-M100	145	60	18	29.9
A-M120	170	60	18	29.9

<i>Hebelstange</i>		
Hebelstange	D	L
HS-M8-12	6	155
HS-M15-20	8	180
HS-M25-40	10	220
HS-M50-65	12	260
HS-M70-120	14	350